

Oil Field Environmental Incident Summary

Incident: 20150622110836

Date/Time of Notice: 06/22/2015 11:08

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: HARLEY 21-2TFH-R

Field Name: BLUE BUTTES

Well File #: 28711

Date Incident: 6/20/2015

Time Incident: 02:30

Facility ID Number:

County: MCKENZIE

Twp: 151

Rng: 95

Sec: 2

Qtr:

Location Description:

Submitted By: TIM HOMISTON

Received By:

Contact Person: TIM HOMISTON

PO BOX 51810

MIDLAND, TX 79710-1810

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	55	Gallons	55	Gallons		

Description of Other Released Contaminant:

Hydraulic Oil

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Low risk due to response kit and volume

Areal Extent:

Contained to 10' X 10' area of ground by coil unit with deployment of spill kit

Potential Environmental Impacts:

Low risk due to response kit and volume

Action Taken or Planned:

Spill kit and vac truck was used to contain and absorb all hydraulic oil.

Wastes Disposal Location: SAFETY CLEAN

Agencies Involved:

Updates

Date: 6/22/2015 ***Status:*** Reviewed - Assigned to Other Agency

Author: Stockdill, Scott

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

According to the incident summary this spill remained on location. NDIC retains oversight.